



STUDENT ID

Andrew Jesky
Printed 1/10/2007



NATEF TASK

VI-EES-F-1

1. Inspect and test gauges and gauge sending units for cause of intermittent, high, low, or no gauge readings; determine necessary action.



4

3



2

1



0



13.0 - 18.0

NATEF VI F 1-4 G 1-3

- A View Electrical Components part 1 video and complete worksheet
- B Read chapter 37 in textbook and complete chapter questions, workbook p. 197-200
- C View Electrical Troubleshooting video and complete worksheet
- D See instructor for review test on chapter 37
- E Complete shop manual Job 136 diagnosing lighting system problems
- F Complete shop manual Job 137 replace and aim headlights